





















BRUNO G20





40 min









Element symbol	Measurements				Code	Pack
1	162	200	16	2	1003-1002	1/ 1
2	702	201	16	1	1001	1/ 1
3	702	201	16	1	1019	1/ 1
4	162	179	16	2	N/ A	1/ 1
5	682	176	3	1	1030_v	1/ 1










► 2





► 3








► 4













► 5



► 5



► 6



► 7

